

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Battle Sports Centre
Address	TN33 0HT

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor
Need for capital investment	Minimal	Moderate	Significant		

Facility Quality	Excellent	Good	Average	Poor	Very Poor
Reception	Excellent	Good	Average	Poor	Very Poor
Sports Hall - 4 Badminton courts	Excellent	Good	Average	Poor	Very Poor
Sudio	Excellent	Good	Average	Poor	Very Poor
Changing rooms	Excellent	Good	Average	Poor	Very Poor
Fitness Suite - 40 stations	Excellent	Good	Average	Poor	Very Poor
Activity Hall	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor

NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED 5

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating
>80%	Excellent
60% - 80%	Good
40% - 59%	Average
20%-39%	Poor
<20%	Very Poor

0%

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Battale Abbey Prep School
Address	TN40 2NH

QUALITY RATING

General Condition	Excellent		Good		Average		Poor		Very Poor	
Need for capital investment	Minimal		Moderate		Significant					

Facility Quality	Excellent		Good		Average		Poor		Very Poor	
Reception	Excellent		Good		Average		Poor		Very Poor	
Swimming Pool	Excellent		Good		Average		Poor		Very Poor	
Crating rooms	Excellent		Good		Average		Poor		Very Poor	
	Excellent		Good		Average		Poor		Very Poor	
	Excellent		Good		Average		Poor		Very Poor	
	Excellent		Good		Average		Poor		Very Poor	
	Excellent		Good		Average		Poor		Very Poor	
	Excellent		Good		Average		Poor		Very Poor	
	Excellent		Good		Average		Poor		Very Poor	
	Excellent		Good		Average		Poor		Very Poor	
	Excellent		Good		Average		Poor		Very Poor	
	Excellent		Good		Average		Poor		Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED										3

Disability Access	Full		Partial		No			
Served by Public Transport	Yes*		No					* a short walk away
Good Natural Presence	Excellent		Good		Average		Poor	
Well Signposted	Good		Some		Poor			
Car Parking	Good		Some		Poor			
Development Potential	Lots		Some		No potential			

Key	Rating
>80%	Excellent
60% - 80%	Good
40% - 59%	Average
20%-39%	Poor
<20%	Very Poor

0%

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Bexhill Academy
Address	TN39 4BY

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor
Need for capital investment	Minimal	Moderate	Significant		

Facility Quality	Excellent	Good	Average	Poor	Very Poor
Reception	Excellent	Good	Average	Poor	Very Poor
Sports Hall - 4 Badminton courts	Excellent	Good	Average	Poor	Very Poor
Studio	Excellent	Good	Average	Poor	Very Poor
Changing rooms	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED					4

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Bexhill College Sports Centre
Address	TN40 2JG

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor
Need for capital investment	Minimal	Moderate	Significant		

Facility Quality	Excellent	Good	Average	Poor	Very Poor
Reception	Excellent	Good	Average	Poor	Very Poor
Sports Hall - 4 Badminton courts	Excellent	Good	Average	Poor	Very Poor
Studios	Excellent	Good	Average	Poor	Very Poor
Changing rooms	Excellent	Good	Average	Poor	Very Poor
Fitness Suite - 71*	Excellent	Good	Average	Poor	Very Poor
Studio	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED					6

* receiving new gym equipment from Millenium so will improve fitness offer

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Bexhill Leisure Centre
Address	TN39 4HS

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor
Need for capital investment	Minimal	Moderate	Significant		

Facility Quality	Excellent	Good	Average	Poor	Very Poor
<i>Reception</i>	Excellent	Good	Average	Poor	Very Poor
<i>Sports Hall - 4 Badminton courts</i>	Excellent	Good	Average	Poor	Very Poor
<i>Studio</i>	Excellent	Good	Average	Poor	Very Poor
<i>Changing rooms</i>	Excellent	Good	Average	Poor	Very Poor
<i>Fitness Suite</i>	Excellent	Good	Average	Poor	Very Poor
<i>Squash courts</i>	Excellent	Good	Average	Poor	Very Poor
<i>Studio</i>	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED					8

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Bexhill Leisure Pool
Address	TN40 2JS

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor
Need for capital investment	Minimal	Moderate	Significant		

Facility Quality	Excellent	Good	Average	Poor	Very Poor
Reception	Excellent	Good	Average	Poor	Very Poor
Swimming Pool	Excellent	Good	Average	Poor	Very Poor
Fitness suite	Excellent	Good	Average	Poor	Very Poor
Changing rooms	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED					4

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Bexhill Youth & Community Centre
Address	TN40 1RE

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor
Need for capital investment	Minimal	Moderate	Significant		

Facility Quality	Excellent	Good	Average	Poor	Very Poor
Reception	Excellent	Good	Average	Poor	Very Poor
Activity Hall	Excellent	Good	Average	Poor	Very Poor
Changing rooms	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor
	Excellent	Good	Average	Poor	Very Poor

NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED 3

*6 in total outside - 4 newly refurbished (excellent) but 2 decommissioned (very poor); 6 inside all good

Disability Access	Full	<input checked="" type="checkbox"/> Partial	No	
Served by Public Transport	Yes*	<input checked="" type="checkbox"/> No		* a short walk away
Good Natural Presence	Excellent	<input checked="" type="checkbox"/> Good	Average	Poor
Well Signposted	Good	<input checked="" type="checkbox"/> Some	Poor	
Car Parking	Good	<input checked="" type="checkbox"/> Some	Poor	
Development Potential	Lots	<input checked="" type="checkbox"/> Some	No potential	

Key	Rating	43%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Buckswood School
Address	TN35 4LT

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Sports Hall	Excellent	Good	Average	Poor	Very Poor	
Swimming Pool	Excellent	Good	Average	Poor	Very Poor	
Changing rooms	Excellent	Good	Average	Poor	Very Poor	
Fitness Suite	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						5

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Cooden Beach Sports & Social Club
Address	TN39 3BD

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Squash courts	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Crowhurst Park
Address	TN33 0SL

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Swimming Pool	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
Health and Fitness	Excellent	Good	Average	Poor	Very Poor	
Studio	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						5

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Dale Hill Hotel and Golf Club
Address	TN5 7DQ

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Swimming Pool	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
Health and fitness	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						4

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Egreton Park Indoor Bowls
Address	TN39 3HL

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Bowls Hall	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Etchingham C of E Primary School
Address	TN19 7BY

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Activity room	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Flackley Ash Hotel Leisure Club
Address	TN31 6YH

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Swimming	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
Health and fitness	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						4

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Gullivars Bowls Club
Address	TN40 1LJ

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Bowls Hall	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Harbour Health Club
Address	TN31 7EL

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Health and Fitness	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
Studio	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						4

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Physiques Gym
Address	TN39 4HU

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Health and fitness	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Poolside Leisure Club
Address	TN39 4TT

QUALITY RATING

General Condition	Excellent	Good	Average		Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant				

Facility Quality	Excellent	Good	Average		Poor	Very Poor	
Reception	Excellent	Good	Average		Poor	Very Poor	
Health and Fitness	Excellent	Good	Average	Poolside Leisure Club	Poor	Very Poor	
Changing Room	Excellent	Good	Average		Poor	Very Poor	
Swimming	Excellent	Good	Average		Poor	Very Poor	
	Excellent	Good	Average		Poor	Very Poor	
	Excellent	Good	Average		Poor	Very Poor	
	Excellent	Good	Average		Poor	Very Poor	
	Excellent	Good	Average		Poor	Very Poor	
	Excellent	Good	Average		Poor	Very Poor	
	Excellent	Good	Average		Poor	Very Poor	
	Excellent	Good	Average		Poor	Very Poor	
	Excellent	Good	Average		Poor	Very Poor	
	Excellent	Good	Average		Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED							4

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Robertsbridge Community College
Address	TN32 5EA

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Sports Hall	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
Activity Hall	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						4

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Rye Lawn Tennis and Squash Club
Address	TN31 7NY

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Squash courts	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Rye Sports Centre
Address	TN31 7ND

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Sports Hall	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
Swimming	Excellent	Good	Average	Poor	Very Poor	
Health and Fitness	Excellent	Good	Average	Poor	Very Poor	
Studio	Excellent	Good	Average	Poor	Very Poor	
Studio	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						7

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	The Precious Sports Hall northiam
Address	TN31 6NB

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Activity Hall	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Vinehall School
Address	TN32 5JL

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Sports Hall	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Westfield Community Centre
Address	TN35 4QJ

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Activity Hall	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Cooden Beach Sports & Social Club
Address	TN39 3BD

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality	Excellent	Good	Average	Poor	Very Poor	
Reception	Excellent	Good	Average	Poor	Very Poor	
Squash courts	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.